



A systematic comparison between EN ISO 12354 calculations of CLT floors with a large set of laboratory and field measurements

Christian Simmons¹

¹ Luleå university of Technology / Simmons akustik & utveckling
{e-mail: info@simmons.se}

Abstract

Within the research projects *AkuLite*, *Aku20* and the current *AkuTimber* at the Luleå university of technology, a large set of field measurement results have been compared to calculations according to EN ISO 12354 -1 and -2. Their agreement was deemed unsatisfactory at first. To try and improve, a new comparison was made between laboratory measurements of various CLT bare floors to establish a semi-empirical prediction model and a small database of sound insulation data for CLT elements with thicknesses 80 to 240 mm. This database was then applied to further comparisons of a new set of field measurements where a well-defined raised floor (measured in a laboratory) had been built on various CLT floors. The comparison was now more stable and a practical safety margin of 5 dB should be enough. All results are presented as average (systematic) deviations and standard deviations of the comparisons. Flanking transmission of walls remain to analyse to conclude a practical prediction procedure of CLT structures.

Keywords: CLT, EN ISO 12354, airborne sound insulation, impact sound insulation

1 Introduction

The acoustic performances of buildings with various types of light weight timber floor have already been studied by many parties, e.g. recently by Homb¹ as well as within the joint European research project Silent Timber Build². They conclude the theoretical SEA-models used in the Silent Timber Build project have severe limitations and they recommend measurements for further analyses of the constructions.

Within the previous research projects *AkuLite* and *Aku20* as well as the current *AkuTimber* at the Luleå university of Technology³, about 30 wooden buildings built since 2010 have been examined by means of detailed field measurements of sound insulations and vibration transmissions.

Those field results gave this author the opportunity to look into one question of practical interest to acoustical consultants: –When consultants apply the most commonly used calculation softwares as well as their general experiences of building acoustics, how close to the real performance can they expect to come, on the average and with which uncertainty? The combination of uncertainties may define a safety margin.

2 Method

In order to make the comparisons between theoretical calculations according to EN ISO 12354 parts 1 and 2 and field measurements, some of the building cases examined in the research projects *Aku20* and *AkuTimber* were selected. Some additional field measurements were contributed by a manufacturer of raised floors, see section 3.4.

- The first estimates of D_{nT} and L_{nT} were made from the drawings only, as a consultant would have to do during an ordinary project design phase (before completion of the building).
- The second estimates were supported by measurement results and vibration transmission measurements to refine the models of the junctions, damping etcetera as would be typical when the purpose is merely to understand unexpected measurement results and to find out which part of a construction needs to be improved, e.g. in the case of the building regulations not being fulfilled.
- The calculated values in the figures below are from “the second estimate”, i.e. some adjustments of input data have been made after comparisons with the measured values and the vibration levels.
- Input data for CLT floors were first calculated on the basis of single laboratory measurements, clause 3.2, then on the basis of a kind of average performances, see clause 3.3.

The calculation tool used to combine elements, define junctions and calculate sound transmission in buildings according to the international standard EN ISO 12354 was Bastian[®] by Datakustik.⁴ For the analyses of floor and wall constructions, the software Insul v9.0.8 by Marshall-Day Acoustics was used.⁵ For analyses of buildings with concrete floors, the semi-empirical data for the elements in the SAU Nordic Database were applied.⁶

3 Results

3.1 Buildings with various CLT floors, example results

Results from field measurements and theoretical calculations of the sound insulation through floors in living rooms of one example building (denominated as “B1”) are presented in Figure 1, in the extended frequency range 20-5000 Hz.

This building is constructed with parquet flooring floating on a 246 mm massive CLT floor and a ceiling with two plasterboards attached to light weight joists that are disconnected from the CLT-floors. Walls are made with double plasterboards and a plywood board, attached on each side of two rows of wooden studs separated by a thin air gap.

Apparently, the calculated values of the airborne sound insulation (thick line) are somewhat on the safe side in the range 50-1000 Hz, but the impact sound insulation values on the other hand seem to be underestimated.

Results from another example building with a different construction (denominated as “B3”) are presented in Figure 2.

Note: The frequency range in Figures 1 and 1 is wider (20-5000 Hz) compared to the standardized range (100-3150 Hz).




Figure 1: (left) 4 measured and 1 calculated standardized airborne sound level differences D_{nT} and (right) standardized impact sound level L_{nT} in building object “B1”.




Figure 2: (left) 4 measured and 1 calculated standardized airborne sound level differences D_{nT} and (right) standardized impact sound level L_{nT} in building object “B3”.

There are no suspended ceilings in the second example building “B3”, but the sound (and fire) insulation of the 150 mm CLT floor has been improved by a 15,4 mm fire plasterboard attached with screws to its bottom face.

The CLT floor is covered by a raised subfloor with a 22 mm chipboard, 30 mm gypsum screed and a parquet flooring on top of joists and elastic pads. The walls are made of 120 mm CLT and plasterboards attached firmly to those, connected to the CLT-floors with thin resilient strips, steel brackets and nails (of stability reasons).

Apparently, the theoretical estimate of the airborne sound insulation is somewhat on the safe side in the mid- frequency range but underestimates the insulation at low and high frequencies. The impact sound insulation is substantially underestimated at all frequencies except the highest, which is of course unsatisfactory.

In this building (B3), looking at the measured values and the vibration transmission results did not really help understand how the construction works from an acoustic point of view. An attempt to find the reason for mismatch was based on the estimated flanking transmissions (as presented by the Bastian software). These results are displayed in Figure 3.




Figure 3: Direct and flanking sound transmissions calculated for object “B3”. The points to the right end of the scale denote the frequency weighted single numbers with spectrum adaptation terms.

It appears in Figure 3, that for the airborne sound insulation, the flanking path f2 via one CLT wall determines the overall result in the range 250-500 Hz, which is physically reasonable to contribute to the thin wall CLT-elements with an expected coincidence limiting frequency in this range (according to Insul).

The other paths may be disregarded from this point of view. From 1000 Hz and higher, the transmission seems to be somewhat exaggerated compared to the measured values, which indicates the resilient material applied under the walls helps to reduce flanking transmission through the junction with the floor at high frequency, in spite of the rather stiff brackets that were nailed to the floor and the wall elements.

Similar observations have been made in a few other projects as well. Certainly, it would be better to find stability measures which allow static forces from wind loads to act but isolates vibrations in the coincidence region.

The raised subfloors with resiliently supported joists and chipboards are efficient in attenuating the impact sound, but of course they cannot do much about a flanking path through the CLT-walls. On the other hand, the impact sound level is underestimated compared to the field measurements.

A closer look at the pictures taken during the construction period indicated there could have occurred short circuiting during the construction of the raised subfloors and the studs for the plaster board walls.

Furthermore, comparison to another building with a similar floor build-up, showed the impact sound level was again underestimated by about 5 dB in a wide frequency range, indicating this construction needs further analysis to find the reason for lower impact sound insulation than expected.

In other projects, the reduced effect of suspended ceilings caused by wall flanking transmission have been realistically indicated with Bastian, but of course the type of junction and data of resilient layers utilized have to be modelled to give correct results. There is an option to enter various modulus of elasticity of junctions with resilient layers in this software, but it remains to examine how a nailed steel bracket should be modelled as a resilient layer with a given E-modulus.

3.2 Average results with all CLT floors

The average results for 23 field measurements of D_{nT} and L_{nT} taken in 8 buildings with CLT structures made in the *AkuTimber* project are presented in Figure 4. Data from the object B3 were included since the kind of error is not uncommon to these kind of constructions. The safety margin plotted in the Figures 4 is the average deviation increased by 1.35 x the standard deviation, in third octave bands as well as the weighted numbers.




Figure 4: Average of differences between 23 sound transmissions measured in 8 buildings with CLT floors compared to the calculated values for each case. The safety margin curve (solid red) for impact sound is truncated above 1 kHz, but this part of the curve is not critical for the single numbers. The single numbers are indicated at the end of the x-scales; $D_{nT,w}+C_{50-3150}$ in the left figure and $L'_{nT,w}+C_{L,50-2500}$ in the right figure.

3.3 Sound insulation of bare CLT floors

One source of uncertainty may be related to the uncertainty of the laboratory data of the bare CLT floors used as input data in the calculations of the sound insulation *in situ*. When various laboratory measurement results taken on more or less similar CLT floors are compared, there are variations between those. To establish a common basis for further comparisons between calculations and field measurements, a database of CLT sound insulation data was deemed necessary to establish.

Thus, calculations with Insul version 9.0.8 were compared to a set of 23 laboratory measurements of airborne sound reduction R (50-5000 Hz) and 29 measurements of impact sound levels L_n (50-5000 Hz), some of them (but not all) where taken in the same laboratories.

After a first round of comparisons, the input parameters of the Young's modulus in two directions were changed to improve the results as compared to the measured data. The input parameters were adjusted to increase the anisotropy, i.e., to widen the gap between the lower frequency of coincidence and the upper frequency. Also, the loss factor was increased somewhat, as suggested by Schoenwald et al.⁷ The comparison between the calculated values and measured in the laboratories are displayed in Figure 5.

The best curve fit was obtained with input data to Insul: ρ : 495 kg/m³, E_1 : 0.20 GPa, E_2 : 16 GPa, η : 0.040, f_{c1} : 63 Hz, f_{c2} : 567 Hz for the airborne sound transmission and ρ : 495 kg/m³, E_1 : 0.55 GPa, E_2 : 22 GPa, η : 0.025, f_{c1} : 54 Hz, f_{c2} : 342 Hz for the impact sound level. Noticeably, those figures are not necessarily the true physical parameters of the CLT, but rather the "tweek" data resulting in a better fit compared to the laboratory measurements.




Figure 5: Average of difference between measured sound transmissions in various laboratories for 23/29 bare CLT floors and the calculated values (with Insul, using adjusted input parameters). The single numbers are indicated at the end of the x-scales ($D_{nT,w}+C_{50-3150}$ in the left figure and $L'_{nT,w}+C_{1,50-2500}$ in the right figure).

To facilitate further calculations of conditions *in situ* in buildings with CLT floors and walls, a database of 17+17 bare CLT floors ranging from 80 to 240 mm, with or without a fire protection plasterboard (12.7 kg/m²) screwed to one side of the CLT, were calculated with Insul and corrected empirically for the average deviations presented in the Figures 5.

Of course, the deviations in results at about 1 kHz, most apparent in the impact sound, would be interesting to examine further, but for now they are only corrected for. This procedure is basically the same as was applied more than 20 years ago to concrete floors and walls,⁹ and the database established then has been used extensively in the Nordic countries over the past 20 years with few modifications.⁶

However, in case this new CLT database should be erroneous in spite of the efforts to mirror their real performances, upcoming comparisons between calculated and field measured sound insulations made in new projects should be collected and analyzed to find whether there are good reasons to adjust this CLT-database. Application of a coordinated set of semi-empirical data facilitates systematic comparisons, which is preferred compared to the present order where different sources of input are used in each project, both for the CLT base structures and the additional floating floors and suspended ceilings.

3.4 Average results with a specific Granab floating floor on various CLT floors

Some complementary analyses with field data have been made of another set of 12 field measurements, made in 7 buildings with similar combinations (although not identical) of a CLT floor and a specific type of floating floor provided by the manufacturer Granab. The CLT data were taken from the new database

presented in clause 3.3. For the floating floor, Granab commissioned laboratory tests with the floor mounted on a CLT 200 mm at RISE in Borås, Sweden, where both ΔR and ΔL_n were measured.

The field data were measured by various acousticians which may add reproducibility errors as indicated in EN ISO 12999-1, but at the same time this natural variation minimize systematic errors when the results are averaged, e.g. measurement procedures, equipment etcetera. A similar comparison was made between calculations and measurements, as in the previous parts of this study. The results are displayed in Figures 6.




Figure 6: Averages of difference between measured sound transmissions in 7 buildings with combinations of a CLT floor and a specific Granab floating floor, compared to the calculated values. The single numbers are indicated at the end of the x-scales ($D_{nT,w} + C_{50-3150}$ in the left figure and $L'_{nT,w} + C_{50-3150}$ in the right figure).

Some observations from Figures 6: The average deviation of the D_{nT} -comparison has a similar tendency as of the data in Figure 4, but the variations between the third octave bands is smaller. The standard deviation of this comparison is substantially lower, which indicates the deviations are stable and could be corrected for (using the mean deviations).

The calculated impact sound levels are substantially lower than measured, which should be corrected for as well. In both the airborne and impact sound insulation results, a standard deviation in the order of 5 dB in third octave bands seem difficult to avoid. The reason for these random variations remains to explain.

The conclusion is that the input data for the floating floor could be corrected for the mean average differences found in Figures 6, which however implies there will be no margin between a calculated value and the expected field measurement. Thus, a calculated result using the corrected data may be fulfilled at a probability of 50% and thus a margin of at least 4-5 dB should be observed during design of a floor construction with this subfloor on a CLT floor where the requirements are strict, and where no deviations will be tolerated. The presented data of the CLT floors and the Granab floor have been included in the database.⁶

3.5 Average results with concrete floors

The uncertainty in weighted single number values of buildings with concrete floors and walls has previously been investigated by this author⁸ as well as others⁹. Since 2004, a safety margin of 3 dB between a calculated insulation and a required value has been recommended by this author to minimize the risk of having underperforming result from field measurements with a probability of about 1 out of 10. Hence, it was certainly challenging to make the same comparison with the new data collected in buildings with concrete floors within the *AkuLite* project. The results in are in line with results from the previous comparisons, and show a good agreement between the theoretical estimates and the field results. However, a 2-3 dB safety margin still appears appropriate to observe during design of a building with concrete floors.




Figure 7: Average of difference between 17 measured sound transmissions made in 7 buildings with concrete floors to the calculated values. The single numbers are indicated at the end of the x-scale ($D_{nT,w}+C_{50-3150}$ in the left figure and $L'_{nT,w}+C_{1,50-2500}$ to the right).

4 Discussion and conclusions

The average agreement between calculated D_{nT} -values and the measured values in laboratories as well as in buildings with CLT-floors have been used to establish input data for calculations with CLT-elements according to the EN ISO 12354 methods. Indications on flanking transmission paths that short circuit suspended ceilings will be a result from such a calculation, but the calculated flanking transmission may be erroneous if the effect of resilient layers at high frequency is not modeled correctly. The results of the comparisons are reasonably satisfying, compared to what this author expected or even feared at first.

As pointed out by Wittstock¹⁰ during data analysis work with the international standard ISO 12999-1, deviations in third octave bands may be assumed partly uncorrelated and the uncertainty in the single numbers should not be estimated from the third octave bands but preferably directly from the collected single numbers.

For concrete floors, the average agreement between measured values and the calculated values for each case is indeed satisfying. The standard deviation is less than 5 dB in the frequency range that determines the single number values (200-800 Hz) and the statistical 90% margin of the single numbers (with a coverage factor 1.35, single sided *Student t*'s distribution of probability) is about 2-3 dB. Thus, the 3 dB margin used since many years, still seem to be applicable. Previously made comparisons indicate that measurement uncertainty (inherent in the ISO 16283 standards) is likely to explain some of the variation, adding to uncertainties inherent in prediction methods, input data, material properties and workmanship errors.

For CLT floors, a provisional safety margin of at least 8 dB should be observed for buildings with more or less unknown layered solutions on top of or below the CLT-floors, unless there are specific experiences of the same construction as is under study that supports a lower margin, in particular the junctions and any type of lining used. It may be questionable whether calculations with such an uncertainty has any meaning at all.

But with a well known construction with a moderate risk of workmanship errors, as for the Granab subfloors with Sylodyn resilient pads presented in Figures 6, a margin of 5 dB may be sufficient to expect 8-9 measurements *in situ* out of 10 to fulfil the requirements, i.e. there is still a 10%-20% risk.

Most noticeably, ΔR and ΔL_n values measured with a lining above or below a heavyweight base construction should not be applied to CLT floors and walls without prior correction for the difference in mobility, which typically means the low frequency sound insulation improvement for the lining may be smaller on a CLT floor than on a concrete floor. For this purpose, a indicative estimate by means of Insul

calculations may be useful but laboratory tests or extensive comparisons with field results are preferred. In the database adapted to the software Bastian, there are now some provisional data for CLT floors as well as for ceilings, wall linings and floating floors, that allow consultants to make their own estimates and compare those to their own field measurements. The intention of presenting data is not intended to “guarantee” accurate predictions but at least allow analyses to identify main transmission paths and risk factors (e.g. constructions sensitive to workmanship). By time, those data may be refined where field results indicate a need for this and the reliability of theoretical estimates may then be improved.

Acknowledgements

The manufacturer of raised floors Bygg- och miljöteknik Granab provided data from both laboratory and field measurements, which is gratefully acknowledged.

References

-
- [1] A. Homb: Hybrid joist floor constructions. Evaluation of measurement results. *Proceedings of the ICA*, Aachen 2019. <http://hdl.handle.net/11250/2625529>
 - [2] K.G. Hagberg et al: *Silent Timber Build*. <https://silent-timber-build.com>
 - [3] *AkuTimber* - Research project at Luleå university of Technology. <https://www.ltu.se/research/subjects/Teknisk-akustik/Forskningsprojekt/Byggnadsakustik>
 - [4] Bastian version 2.3.107. Datakustik. <http://www.datakustik.com>
 - [5] Insul version 9.0.8. Marshall Day Acoustics. <http://www.insul.co.nz>
 - [6] SAU Nordic Database for calculations according to EN ISO 12354. <http://www.bastian.nu>
 - [7] Schoenwald, S et al. Sound insulation performance of Cross Laminated Timber Building Systems. *Proceedings of the inter-noise 2013*, Innsbruck September 2013
 - [8] C. Simmons: Managing uncertainty in building acoustics - Comparisons of predictions using the EN 12354 standards to measurements. *Ph.D thesis*, Luleå University of Technology 2009. <http://www.dissertations.se>
 - [9] D.B. Pedersen et al: Nordic basis of calculation of sound insulation in buildings (NT TR 425). <http://www.nordtest.info>
 - [10] V. Wittstock: Determination of Measurement Uncertainties in Building Acoustics by Interlaboratory Tests. Part 1: Airborne Sound Insulation. *Acta Acustica united with Acustica* Vol 101(1) 2015.